

Job Description

Job Title: Weld Operator (Machine Operator)

Reports To: Weld Supervisor

Division: Weld Department

Location: 123 West Boxhorn Drive, Mukwonago, WI 53149

Pay: \$23/hr

To Apply: send resume to egreil@bankerwire.com

Summary: Performs work on the Mesh Welder machines by completing the following job duties as directed by the Weld Line Supervisor by performing the following duties.

Summary: This position would be running an automatic resistance welder. Making sure that wires are consistently being welded properly and ensuring that production is continuous. This position is vital to our quality assurance, as all quality-related steps must be performed by the operator. All training for this role will be done on-site. The right candidate must be able to work with basic math formulas, decimal and fraction conversion, and precise accuracy when reading a tape measure.


Work Experience: Must have proven mechanical experience, or hands-on experience working with metal.

Requirements:

1. **Must be able to read a tape measure with precise accuracy**
2. Ability to lift up to 50lbs repetitively
3. Available to work overtime, as needed (2x a month on Saturday's)

Skills and Qualifications:

4. Reliable
5. Mechanically inclined
6. Attentive to detail
7. Hands-on learner
8. Able to retain and apply training information
9. Ability to work in a fast-paced environment



Duties and Responsibilities: Other duties may be assigned

- Basic setups of the Jig and Mesh Welder machines.
- Retrieve wire from the Staging Area during change overs. Check job sheet for correct wire
- Load line wires in to the appropriate fixtures/guides
- Complete all required paperwork in a timely manner
- Retrieve pallets for next job during changeovers. Clean work area during machine downtime
- (Sweeping, garbage, wipes down machines; organize wire staging area, etc.)
- Assist the Set-Up Technician as needed and/or directed by Weld Line Supervisor
- Consistently strive for high production numbers while producing high quality/zero defect parts
- Follow all safety procedures and ensure cleanliness and proper maintenance of the work areas. Clean the Weld Line Area at the end of each shift
- Unload finished product (up to 50 lbs.) from welders; stack, band and transport as necessary
- Perform all necessary quality checks as directed by the Weld Line Supervisor and/or Setup Technician
- Maintain a neat and orderly work space

Physical Demands: The physical demands described here are representative of those that must be met by the employee to successfully perform the essential functions of this job. Reasonable accommodations may be made to enable individuals with disabilities to perform the essential functions. The employee must be able to lift up to 50lbs. The employee must also be able to: reach, stoop, bend, climb stairs/ladders, pull, carry, walk and stand for extended periods of time. Eye-hand coordination and finger dexterity are required. The employee must also be able to tolerate extreme temperatures.

Work Environment: Noise levels range from low to high. Extreme temperature conditions will be incurred during summer months, potentially for the entire shift in the shop area. The shop environment has the potential for safety hazards and being dusty and dirty. The employee will encounter lengthy intervals of standing on concrete floors.